Monday, 29/09/2008 8:29:23 AM

Jean-Luc Menard

: 11

: 42213

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number : 42314

Estimate Number

: 10791

P.O. Number

This Issue

: 29/09/2008

: NC Prsht Rev.

First Issue **Previous Run**

Written By

Checked & Approved By

Comment

: Est Rev:B 05.09.23

Type

: SKIDTUBES

Due Date

Part Number Drawing Number

Drawing Name

: D3282 REV C : N/A

: C

: FLOAT WEB

: D3282041

Project Number Drawing Revision

Material

: 06/10/2008

Qty:

Each

Additional Product

Job Number:



D2792130

Seq. #: 1:0

Machine Or Operation:

Description:

EXTRUSION

Procedure change KJ/JLM

٢

Comment: Qty.:

1.0000 Each(s)/Unit

Total:

10.0000 Each(s)

Pick:

SKIDTUBES 1

Qty Part Number 1 D2792-130

Description

Batch 718 Extrusion_

Identify as D3282-1

SKIDTUBESS RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Cut to length as per Dwg D3282.

2- inspect for surface damage as per QSI0018

08-09-29

3.0

2.0

HAAS1

HAAS CNC VERTICAL MACHINING #1



Comment: HAAS CNC VERTICAL MACHINING #1

1-Machine as per Folio FA579 & Dwg D3282

2-Deburr

QC2

INSPECT PARTS AS THEY COME OFF MAC

2T.08-09-28

4.0

Comment: INSPECT PARTS AS THEY COME OFF MACHINE



Monday, 29/09/2008 8:29:23 AM Date: User: Jean-Luc Menard **Process Sheet Drawing Name: FLOAT WEB** Customer: CU-DAR001 Dart Helicopters Services Part Number: D3282041 Job Number: 42314 Job Number: Description: Seq. #: **Machine Or Operation:** SECOND CHECK 5.0 QC8 08/10 Comment: SECOND CHECK HAND FINISHING RESOURCE #1 HAND FINISHING1 8-10-3 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION 7.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION D32831 Doubler 8.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s) Pick: Description **Qty Part Number** Batch Doubler 2 D3283-1 MS20470AD47 Rivet, Universal Head 9.0 Comment: Qty.: 57.0000 Each(s)/Unit Total: 570.0000 Each(s) Pick: **Qty Part Number** 8-10-12 57 MS20470AD4-7 10.0 SKIDTUBES 1 Comment: L'ANDING GEAR RESOURCE 1 1-Install doublers as per Dwg D3282. Apply LPS-3 between doublers and web SL & 10-12 AVRN/ALPS-3 M 10 3674 QC5 INSPECT WORK TO CURRENT STEP 11.0

Comment: INSPECT WORK TO CURRENT STEP

Date:

Monday, 29/09/2008 8:29:23 AM

User:

Jean-Luc Menard

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT WEB

Job Number: 42314

Part Number: D3282041

Job Number:



Seq. #:

Machine Or Operation:

Description:

12.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock Location: L. 6 8-12-10



13.0

Job Completion

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE



08/10/15/g) ME 08-10-15







DART AEROSPACE LTD	Work Order:	42314	
Description: Float Web	Part Number:	D3282-041	
Inspection Dwg: D3282 Rev: C		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension		Dimension	•		Inspection	
126.6	+/-0.100	126.660				
1.500	+/-0.010	1.500				
3.000	+/-0.010	3.000				
6.000	+/-0.010	6.000				
1.250	+/-0.010	1.250				
30.000	+/-0.010	30.000				
1.500	+/-0.010	7.500				
72.01	+/-0.030	72.010				
61.75	+/-0.030	61.750	/			
57.50	+/-0.030	57,500				
49.19	+/-0.030	49.190		yes made a second		
43.94	+/-0.030	43.940				
39.69	+/-0.030	39.690				
26.68	+/-0.030	26.680				
0.55	+/-0.030	0.550				
1.970	+/-0.010	1.970				
2.38	+/-0.030	2.378				
0.05	+/-0.030	.050				

Measured by:	and !	Audited by:		Prototype Approval:	N/A
Date:	0809/29	Date:	08/10/01	Date:	N/A.

Г	Rev	Date	Change	Revised by	Approved
Γ	Α	07.04.02	New Issue	KJ/JLM a	Cull
_		···			7,0.7

W/O:		WORK ORDER CH	IANGES				1	
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	/ Approvai	

Part No: D3282-041 PAR #: NA Fault Category: Fod Hach and Park NCR: Yes No DQA: Date: 08/0/16

Resolution: ______ Disposition: ______ QA: N/C Closed: ______ Date: 08/0/16

NCR: 4	2314	WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section B Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector			
06-10-01	4.0			Scrap: No replace. set up already tore dwa on the HAAS.	5.F)	1.5. 10/10/80	Pasionz	108-10-0			
8/10/p1	4.0.	Proter web. One uch is mark by deill chuch, 0020" DEEP CIRCULAR DENT \$ \$1.375. R.C. operator error	JULIUL	SCRAP TUBE DIMG IN MIDDLE SPAN OF TUBE. MATIL LOOKS STRETCHED. 48.09.01	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	J.L 08/10/01	Postup	1051001			

NOTE: Date & initial all entries